



CT042

14" X 40" 3-HP LATHE

User Manual



COPYRIGHT © 2010 BY CRAFTEX INDUSTRIES INC. NO PORTION OF THIS MANUAL MAY BE PRODUCED WITHOUT THE WRITTEN CONSENT OF CRAFTEX INDUSTRIES INC.



WARNING

1. Read and understand the entire instruction manual before operating machine.
2. Always wear approved safety glasses/face shields while using this machine.
3. Make certain the machine is properly grounded.
4. Before operating the machine, remove tie, rings, watches, other jewelry, and roll, up sleeves above the elbow. Remove all loose clothing and confine long hair. Do not wear gloves.
5. Keep the floor around the machine clean and free of scrap material, oil and grease.
6. Keep machine guards in place at all times when the machine is in use. If removed for maintenance purposes, use extreme caution and replace the guards immediately.
7. Do not over reach. Maintain a balanced stance at all times so that you do not fall or lean against blades or other moving parts.
8. Make all machine adjustment or maintenance with the machine unplugged from the power source.
9. Use the right tool. Don't force a tool or attachment to do a job which it was not designed for.
10. Replace warning labels if they become obscured or removed.
11. Make certain the motor switch is in the OFF position before connecting the machine to the power supply.
12. Give your work undivided attention. Looking around, carrying on a conversation, and "horse-play" are careless acts that can result in serious injury.
13. Keep visitors a safe distance from the work area.
14. Use recommended accessories; improper accessories may be hazardous.
15. Make a habit of checking to see that keys and adjusting wrenches are removed before turning on the machine.
16. Never attempt any operation or adjustment if the procedure is not understood.
17. Keep fingers away from revolving parts and cutting tools while in operation.
18. Keep belt guard in place and in working order.
19. Never force the cutting action.
20. Do not attempt to adjust or remove tools during operation.
21. Always keep cutters sharp.
22. Always use identical replacement parts when servicing.
23. Failure to comply with all of these warnings may cause serious injury.

Specifications:		GH-1440A(C6236A2)
Capacities:		
Swing Over Bed		14"(356mm)
Swing Over Cross Slide		8-5/8"(220mm)
Swing Over Gap		20"(506mm)
Length of Gap		9-3/8"(238mm)
Distance Between Centers		40"(1000mm)
Headstock:		
Hole Through Spindle		1-1/2"(38mm)
Spindle Nose		D1-4Camlock
Taper in Spindle Nose		MT-5
Spindle Bearing Type		Taper Roller Bearing
Number of Spindle Speeds		8 or 16
Range of Spindle Speeds		90 or 45~1800RPM
Gearbox:		
Number of Longitudinal and Cross Feeds		40
Range of Longitudinal Feeds		0.0012"~0.0294"(0.043~0.653mm)
Range of Cross Feeds		0.0004"~0.0108"(0.015~0.22mm)
Number of Inch Threads		40(28)
Range of Inch Threads		4-112T.P.I
Number of Metric Threads		22(37)
Range of Metric Threads		0.45~7.5mm(0.4~7mm)
Leadscrew		7/8"×49-1/2"(22mm×1258mm)
Feed Rod Diameter		3/4"(19mm)
Compound and Carriage		
Toolpost Type		4-Way
Maximum Tool Size		5/8"×5/8"(16×16mm)
Maximum Compound Slide Travel		3-1/2"(90mm)
Maximum Cross Slide Trave		7"(180mm)
Maximum Carriage Trave		37-1/2"(950mm)
Tailstock:		
Tailstock Spindle Travel		4-3/4"(120mm)
Diameter of Tailstock Spindle		1-25/32"(45mm)
Taper in Tailstock Spindle		MT-3
Miscellaneous:		
Steady Rest Capacity		1/4"~2-5/8"(6.5~65mm)
Follow Rest Capacity		1/4"~2-3/4"(6.5~70mm)
Length of Bed		54-1/4"(1380mm)
Width of Bed		8"(203mm)
Height of Bed		11"(280mm)
Overall Dimensions		71-3/4L×30"W×48"H
Main Motor power		1825mm×760mm×1213mm
Net Weight(approx.)		3HP(2.2kW)
Shipping Weight(approx.)		1650lbs.(750kg)
		1936lbs.(880kg)

Note: Data in the parentheses are for metric system.

Table of Contents

Safety Warnings.....	1
Specifications.....	2-3
Table of Contents.....	4
Uncrating and Clean-Up.....	5
Chuck Preparation.....	6
Lubrication.....	7
Electrical Connections.....	8
General Description.....	9-11
Controls.....	11-14
Break-in Procedure.....	14
Operation.....	14-16
Adjustments.....	16-20

⚠️ WARNING

Read and understand the entire contents of this manual before attempting set-up or operation!

Failure to comply may cause serious injury!

Uncrating and Clean-Up

1. Finish removing the wooden crate from around the lathe.
2. Unbolt the lathe from the shipping crate bottom.
3. Choose a location for the lathe that is dry, has good lighting and has enough room to be able to service the lathe on all four sides.
4. Sling lathe after placing steel rods or pipes(of sufficient strength)into holes of lathe stand as diagrammed in Fig. 1 .Do not lift by spindle.
With adequate lifting equipment, slowly raise the lathe off the shipping crate bottom. Make sure lathe is balanced before moving.
5. To avoid twisting the bed,the lathe's location must be absolutely flat and level. Check for a level condition using a machinist's precision level on the bedways both front to back and side to side. The leveling pads included in the tool box and the leveling screws in the lathe base will help you to reach a level condition. The lathe must be level to be accurate.
6. Clean all rust protected surfaces using a mild commercial solvent, kerosene or diesel fuel. Do not use paint thinner, gasoline, or lacquer thinner. These will damage painted surfaces. Cover all cleaned surfaces with a light film of 20W machine oil.
7. Remove the end gear cover. Clean all components of the end gear assembly and coat all gears with a heavy, non-slinging grease. Replace cover.




Fig.1

Chuck Preparation(Three Jaw)



WARNING

Read and understand all directions for chuck preparation!

Failure to comply may cause serious injury and/or damage to the lathe!

1. Support the chuck while turning three camlocks 1/4 turn counter-clockwise with the chuck key enclosed in the tool box.
2. Carefully remove the chuck from the spindle and place on an adequate work surface.
4. Inspect the camlock studs. Make sure they have not become cracked or broken during transit. Clean all parts thoroughly with solvent. Also clean the spindle and camlocks.
5. Cover all chuck jaws and scroll inside the chuck with #2 lithium tube grease. Cover the spindle, cam locks, and chuck body with a light film of 20W oil.
6. Lift the chuck up to the spindle nose and press onto the spindle. Tighten in place by turning the cam locks 1/4 turn clockwise. The index mark (A, Fig.2) on the camlock should be between the two indicator arrows (B, Fig.2). If the index mark is not between the two arrows, remove the chuck and adjust the camlock studs by either turning out one full turn (if cams will not engage) or turning in one full turn (if cams turn beyond indicator marks).
7. Install chuck and tighten in place.




Fig.2

Lubrication

CAUTION

Lathe must be serviced at all lubrication points and all reservoirs filled to operating level before the lathe is put into service!

Failure to comply may cause serious damage to the lathe!

- Headstock**-Oil must be up to indicator mark in oil sight glass (A,Fig.3). Top off with Shell Turbo T-68 or equivalent. Fill by pulling plug(B,Fig.3). To drain, remove drain plug(A, Fig.4)with an 8mm hex wrench. Drain oil completely and refill after the first three months of operation. Then, change oil in the headstock annually.
- Gearbox Input Shaft**-Remove end gear cover and oil the gearbox input shaft where it exits the headstock bracket(B,Fig.4)with the oil can using 20W machine oil. Oil once daily.
- Gearbox**-Oil must be up to indicator mark in oil sight glass(C,Fig.3). Top off with Shell Turbo T-68 or equivalent. Fill by removing plug (C,Fig.4)with an 8mm hex wrench. To drain, remove drain plug(D,Fig.4)with an 8mm hex wrench. Drain oil completely and refill after the first three months of operation. Then, change oil in the gearbox annually.
- Apron**-Oil must be up to indicator mark in oil sight glass (front of apron-A,Fig.5). Top off with Shell Turbo T-68 or equivalent. Remove oil cap(B,Fig.5) on top of apron to fill. To drain, remove drain plug on bottom of apron. Drain oil completely and refill after the first three months of operation. Then, change oil in the apron annually.
- Leadscrew Feed Rod**-lubricate ball oiler(D, Fig.3)on leadscrew/feed rod bracket with 20W machine oil once daily.
- Cross Slide**-Lubricate three oil ports(C, Fig.5)with 20W machine oil once daily.
- Compound Rest**-lubricate one oil port (D,Fig.5)with 20W machine oil once daily.




Fig.3




Fig.4




Fig.5

8. **Carriage**-lubricate four oil ports(A,Fig.6)with 20W machine oil once daily.
9. **Tailstock**-lubricate two oil port(B,Fig.6)with 20W machine oil once daily.

Coolant Preparation

CAUTION

Follow coolant manufacturer's recommendations for use,care, and disposal.

1. Remove rear access cover on tailstock end. Make sure coolant tank has not shifted during transport and is located properly under recovery chute.
2. Pour three gallons of coolant mix into drip pan.
3. After machine has been connected power, turn on coolant pump and check to see coolant is cycling properly.
4. Fasten coolant door to stand.




Fig.6

Electrical Connections

WARNING

All electrical connections must be completed by a qualified eletrcian!

Failure to comply may cause serious injury and/or damage to the machinery and property!

The GH-1340A gear head lathe is rated at 3HP. Confirm power available at the lathe's location is the same rating as the lathe.

Make sure the lathe is properly grounded.

Power is connected properly when pulling up on the forward-reverse lever causes the apindle to rotate counter-clockwise as viewed from the tailstock. If the chuck rotates in the clockwise direction, disconnect the lathe from the power source, switch two of three power leads, and connect the lathe to the power source.

General Description

Lathe Bed

The lathe bed(A,Fig.7)is made of high grade cast iron. By combining high cheeks with strong cross ribs, a bed with low vibration and high rigidity is realized . Two precision ground vee slideways, reinforced by heat hardening and grinding, are an accurate guide for the carriage and headstock. The main drive motor is mounted in the stand below headstock.

Headstock

The headstock (B,Fig.7)is cast from high grade, low vibration cast iron. It is bolted to the bed by four screws with two adjusting screws for alignment. In the head, the soindle is mounted on two precision taper roller bearings. The hollow spindle has Morse Taper # 5 with a 1-7/16" bore.

Carriage

The carriage(A,Fig.8)is made from high quality cast iron. The sliding parts are smooth ground. The cross-slide is mounted on the carriage and moves on a dovetailed slide which can be adjusted for play by means of the gibbs.

The top slide(B,Fig.8),which is mounted on the cross slide (C,Fig.8),can be rotated through 360°. The top slide and the cross slide travel in a dovetail slide and have adjustable gibbs. A four way tool post is fitted on the top slide.

Four Way Tool Post

The four way toolpost(D,Fig.8)is mounted on the top slide and allows a maximum of four tools to be mounted simultaneously. Remember to use a minimum of two clamping screws when installing a cutting tool.

Apron

The apron(E,Fig.8)is mounted to the carriage. In the apron a half nut is fitted. The half nut gibbs can be adjusted from the outside. The half nut is engaged by use of a lever. Quick travel of the apron is accomplished by means of a bed mounted rack and pinion, operated by a hand wheel on the front of the apron.




Fig.7




Fig.8

Tailstock

The tailstock(A, Fig.9) slides on a v-way and can be locked at any location by a clamping lever. The tailstock has a heavy duty spindle with a Morse Taper #3.

Leadscrew and Feed Rod

The leadscrew(B Fig. 9) and feed rod (C, Fig 9)are mounted on the front of the machine bed. They are connected to the gearbox at the left for automatic feed and lead and are supported by bushings on both ends. Both are equipped with brass shear pins.

Gear Box

The gear box(D, Fig.9)is made from high quality cast iron and is mounted to the left side of the machine bed.

Steady Rest

The steady rest (E, Fig.9)serves as a support for shafts on the free tailstock end . The steady rest is mounted on the bedway and secured from below with a bolt , nut and locking plate. The sliding fingers require continuous lubrication at the contact points with the workpiece to prevent premature wear.
To set the steady rest:

1. Loosen three hex socket cap screws.
2. Loosen knurled screw and open sliding fingers until the steady rest can be moved with its fingers around the workpiece. Secure the steady rest in position.
3. Set the fingers snugly to the workpiece and secure by tightening three hex socket cap screws. Fingers should be snug but not overly tight. Lubricate sliding points with lead based grease.
4. After prolonged use , the fingers will show wear. Remill or file the tips of the fingers.

Follow Rest

The traveling follow rest(F, Fig.9)is mounted on the saddle and follows the movement of the turning tool. Only two fingers are required as the place of the third is taken by the turning tool . The follow rest is used for turning operations on long,slender




Fig.9

workpieces. It prevents flexing of the workpiece from the pressure of the cutting tool.

The sliding fingers are set similar to the steady rest, free of play, but not binding. Always lubricate adequately with lead based grease during operation.

Controls

1. **Control Panel**-located on front of headstock.

A.Coolant On-Off Switch(A,Fig.10) turns coolant pump on and off.

B.Power Indicator Light(B,Fig.10)-lit whenever lathe has power.

C.Emergency Stop Switch(C,Fig.10)-depress to stop all machine functions. (Caution: lathe will still have power). Twist to re-set.

D.Jog Switch(D,Fig.10)-depress and release to advance spindle momentarily.

2. **Headstock Gear Change Levers**(E,Fig.10)-located on front of headstock at the top.Move levers left or right to desired spindle speed.

3. **Leadscrew/Feedrod Directional Lever**(F,Fig.10)-located on front of headstock. Moving the lever up causes carriage travel toward the tailstock. Moving the lever down causes carriage travel toward the headstock. Do not move lever while machine is running.

4. **Feed/Lead Selector Lever**(G,Fig.10)-located on the front of the headstock at the top. Used whenever setting up for threading or feeding. Caution: in the "A"position, never run the lathe higher than 770 RPM.

5. **Feed/Lead Selector Lever**(H,Fig.10)-located on the front lower right corner of the headstock. Used in setting up for feeding and threading. Positions "F"and"D"are for the feed rod. Positions "E"and"C"are for the feed screw. Position "0" is neutral.




Fig.10

6. **Lock Knob**(A,Fig.11)-located on the front of the gearbox. With the lever in the six o'clock position, lead/feed selector knob (B,Fig.11)may be adjusted. With the lever in the twelve o'clock position, the lead/feed selector knob(B,Fig.11)is locked.
7. **Feed/Lead Selector Knob**(B,Fig.11)-located on front of the gearbox. Use for setting up for feeding and threading.
8. **Compound Lock**(A,Fig.12)-hex socket cap screw located on left side of compound rest. Turn clockwise to lock and counter-clockwise to unlock.
9. **Carriage Lock**(B,Fig.12)-lock handle located on top of carriage. Turn clockwise to lock. Turn counter-clockwise to unlock. **Caution:** carriage lock must be unlocked before engaging automatic feeds or damaged to lathe may occur.
10. **Cross Slide Lock**(C,Fig.12)-set screw located on right side of cross slide body. Turn clockwise and tighten to lock. Turn counter-clockwise and loosen to unlock. **Caution:**cross slide lock screw must be unlock before engaging automatic feeds or damage to the lathe may occur.
11. **Longitudinal Traverse Hand Wheel** (D,Fig.12)-located on the apron assembly. Rotate hand wheel clockwise to move the apron assembly toward the tailstock(right). Rotate the wheel counter-clockwise to move the apron assembly toward the headstock(left).
12. **Feed Selector**(E,Fig.12)-located in the center front of the apron assembly. Push lever to the left and down activates the crossfeed function. Pull lever to the right and up activates the longitudinal function.
13. **Half Nut Engage Lever(Thread Cutting)** (F,Fig.12)-located on front of the apron. Move the lever down to engage. Move the lever up to disengage.
14. **Cross Traverse Handwheel**(G,Fig.12)-located above the apron-assembly. Clokwise rotation moves the cross slide toward the rear of the machine.



Fig.11




Fig.12

15. Compound Rest Traverse Handwheel

(H, Fig. 12)- located on the end of the compound slide. Rotate clockwise or counter-clockwise to move or position.

16. Tool Post Clamping Lever (J, Fig. 12) -

located on top of the toolpost. Rotate counter-clockwise to loosen and clockwise to tighten.

17. Tailstock Quill Clamping Lever (A, Fig.13) -

located on the tailstock. Lift up to lock the spindle. Push down to unlock.

18. Tailstock Clamping Lever(B, Fig.13)-

located on the tailstock. Lift up lever to lock. Push down lever to unlock.

19. Tistock Quill Traverse Handwheel

(c, Fig.13) - located on the tailstock. Rotate clockwise to advance the quill. Rotate counter-clockwise to retract the quill.

20. Tailstock Off-Set Adjustment (D, Fig. 13) -

two hex socket cap screws located on the tailstock base are used to off-set the tailstock for cutting tapers. Loosening one screw while tightening the other off sets the tailstock.

21. Foot Brake (A, Fig. 14)- located between stand pedestals. Dwpres to stop all lathe functions.

22. Power Switch (not shown) - located on the electrical box on the rear of the lathe. Turns main power to the lathe on and off.

23. Two Speed Motor Swith (B, Fig.14)located on front of the left base pedestal. Position one is for high speed. Position two is for low speed. Position zero is neutral and the spindle will not turn. **Note:**Check this switch and make sure position one or two is selected if the lathe will not run.

24. Micro Carriage Stop (A, Fig.15) - located on the lathe bed. Loosen two hex socket cap screws underneath body and slide along bed to desired position. Tighten screw to hold in place.




Fig.13




Fig.14




Fig.15

Break-In Procedure

During manufacture and testing, this lathe has been operated in the low R.P.M. range for three hours.

To allow time for the gears and bearings to break-in and run smoothly, do not run the lathe above 770 R.P.M. for the first six hours of operation and use.

Operation

Feed and Thread Selection

1. Reference the feed and thread tables (A, Fig. 16) found on the gear box faceplate.
2. Move levers (B,C,D,& E, Fig. 16) to the appropriate positions according to the chart.

Change Gears Replacement

Note: the 25T \times 127T \times 50T gears are installed in the end gear compartment when delivered from the factory. This combination will cover most inch feeds and threads under normal circumstances. The 30, 32, two 40 tooth gears and other gears found in the tool box are used as indicated on feed and thread tables (A, Fig. 16).

1. Disconnect the machine from the power source.
2. Remove the end cover on the left end of the headstock.
3. Loosen nuts (A & B, Fig. 17).
4. Move quadrant (C, Fig. 17) out of the way and hold in place temporarily by tightening nut (B, Fig. 17).
5. Remove hex socket cap screws (D and/or E, Fig. 17), depending on which gear is to be changed.
6. Install new gear(s) and tighten in place with a hex socket cap screw.
7. Loosen nut (B, Fig. 17), move quadrant back so teeth mesh on gears, and tighten nuts (A & B, Fig. 17). **Caution: Make sure there is a backlash of .002"-.003" between gears, Setting the gears too tight will cause excessive noise and wear.**




Fig.16




Fig.17

7. Install the cover and connect the machine to the power source.

Note: other gear combinations are possible. See the lead and feed chart on the front of the gear box (A, Fig. 16).

Automatic Feed Operation and Feed Changes

1. Move the forward/reverse selector (A, Fig. 18) up or down depending on desired direction.
2. Set selector levers (A,B,C,&D,Fig.19) to desired rate. **Note:** for feeding, lever(C) will be set at "F" or "D", depending on desired feed rate.

Powered Carriage Travel

1. Push lever(B,Fig.18) to the left and down to engage crossfeed. Pull lever to the right and up to engage longitudinal feed.

Thread Cutting

1. Set forward/reverse lever (A,Fig.19) up or down depending on the desired direction.
2. Set selector levers (A,B,C, and D, Fig.19) to desired rate. Note: for threading, lever(C) will be set at "C" or "E", depending on desired thread.
3. Engage the half nut lever(C,Fig.18).
4. To cut inch threads, refer to the chart on page 16. The half nut lever and the threading dial are used to thread in the conventional manner. The thread dial chart specifies at which point a thread can be entered using the threading dial.
5. To cut metric threads, the half nuts must be left continually engaged once the start point has been selected and the half nut is initially engaged (thread dial cannot be used).




Fig.18




Fig.19

Inch Gear Box:

Metric Thread Table

MM → ←	127		127		127	
	50 (40)	40 (32)	50 (40)	50 (40)	45 (30)	60 (40)
1	3	6	3	1	2	3
AC	7.5	6.0	5.0	4.8	4.5	4.0
BC	3.75	3.0	2.5	2.4	2.25	2.0
AE		1.5	1.25	1.2		1.0
BE		0.75		0.6		0.5
						0.45

Inch Lead and Feed Table

→ ← T.P.I.		IN → ←		1	2	3	4	5	6	7	8
127 50 (40) 50 (40)	A	C	4	4½	5	5½	5¾	6	6½	7	
	D		.0294	.0261	.0235	.0214	.0205	.0196	.0181	.0168	
	A	C	8	9	10	11	11½	12	13	14	
127 30 (25) 60(50)	D		.0147	.0131	.0117	.0107	.0102	.0098	.0090	.0084	
	B	C	16	18	20	22	23	24	26	28	
	D		.0073	.0065	.0058	.0053	.0051	.0049	.0045	.0042	
A	E	32	36	40	44	46	48	52	56		
	F		.0042	.0038	.0034	.0031	.0030	.0028	.0026	.0024	
	B	E	64	72	80	88	92	96	104	112	
B	F		.0021	.0019	.0017	.0015	.0015	.0014	.0013	.0012	

Note: The tooth numbers in the parentheses are for GH-1340A lathes

Metric Gear Box :

→ ← MM			MM → ←							TPI → ←																	
	1	2	3	4	6	7	8		1	2	3	4	6	7	8		2	1	2	2	1	1	1				
30T 127T	C	A	4.0	4.5	5.0	5.5	6.0	6.5	7.0	D	A	0.375	0.428	0.466	0.513	0.561	0.606	0.653	C	A	4	4½	5	5½	6	6½	7
		B	2.5	2.25	2.5	2.75	3.0	3.25	3.5		B	0.188	0.214	0.233	0.256	0.280	0.303	0.327		B	8	9	10	11	12	13	14
60T	E	A	1.0	1.125	1.25	1.375	1.5	1.625	1.75	F	A	0.109	0.122	0.135	0.149	0.163	0.177	0.190	E	A	16	18	20	22	24	26	28
		B	0.5		0.625		0.75		B	0.054	0.060	0.067	0.074	0.061	0.088	0.095	B	32	36	40	44	48	52	56			
24T 127T 60T	E	A	0.8	0.9	1.0	1.1	1.2	1.3	1.4	F	A	0.087	0.098	0.109	0.119	0.131	0.141	0.152									
		B	0.4	0.45	0.5	0.55	0.6	0.65	0.7		B	0.043	0.049	0.054	0.059	0.065	0.071	0.076									

Compound Rest

The compound rest (A, Fig.20) is located on top of the carriage and can be rotated 360 degrees. There is a calibrated dial (in degrees) (B, Fig.20) below the rest to assist in placement of the compound to the desired angle.

Adjustments

After a period of time, wear in some of the moving components may need to be adjusted:

Saddle

1. Loosen four hex nuts found on the bottom rear of the cross slide and back off one full turn each
2. Turn each of the four set screws with a hex wrench until a slight resistance is felt. Do not over tighten these screws.




Fig.20

3. Move the carriage with the hand wheel and determine if the drag is to your preference. Readjust the set screws as necessary to achieve the desired drag.
4. Hold the socked set screw firmly with a hex wrench and tighten the hex nut to lock the set screw in place.
5. Move the carriage again and adjust again if necessary. **Note:** over adjustment will cause excessive premature wear of the gibbs.

Cross Slide

If the cross slide is too loose, follow procedure below to tighten:

1. Loosen the rear gib screw approximately one turn.
2. Tighten the front gib screw(B, Fig.21)a quarter turn. Turn the cross slide handwheel to see if the cross slide is still loose. If it is still loose, tighten the front screw a bit more and try again.
3. When the cross slide is properly adjusted, tighten the rear gib screw. Do not over tighten. This will cause premature wear on the gib and mating parts.

Compound Rest

Follow the same procedure as the cross slide adjustment to adjust the compound rest. Rear gib screw(B) is shown in Fig. 21. **Note:** the front handwheel on the compound will have to be removed to access the front gib screw.

Tailstock

If the handle will not lock the tailstock, follow the procedure below:

1. Lower the handle to the unlocked position.
2. Slide the tailstock to an area that allows access to the underside of the tailstock.
3. Tighten tailstock clamping bolt 1/4 turn. Test for proper locking. Repeat as necessary.




Fig.21

Tailstock Off-Set

Follow the procedure below to off-set the tailstock to cut shallow tapers:

1. Lock tailstock in position by raising locking handle(A, Fig.22)
2. Alternately loosen and tighten front and rear hex socket cap screws(B, Fig.22).

Tailstock Gibs

Take up play in the tailstock by tightening two gib screws(C, Fig.22) on either side of the tailstock base. Note: Do not over tighten. Excessive tightening will lead premature wear of the gib and mating parts.




Fig.22

Headstock Alignment

The headstock has been aligned at the factory and should not require adjustment. However, if adjustment is deemed necessary, follow the procedure below to align the headstock:

1. Using a machinist's precision level on the bedways, make sure the lathe is level side to side and front to back. If the lathe is not level, correct to a level condition before proceeding. Re-test alignment if any leveling adjustments were made.
2. From steel bar stock of approximately two inches in diameter, cut a piece approximately eight inches long.
3. Place two inches of bar stock into chuck and tighten chuck. Do not use the tailstock or center to support the other end.
4. Set up and cut along five inches of the bar stock.
5. Using a micrometer, measure the bar stock neck to the chuck and at the end. The measurement should be the same.
6. If the measurements are not the same and adjustment is required, loosen hex socket cap screws(A, Fig.23) which hold the headstock to the bed. Do not loosen completely; some drag should remain.





Fig.23

7. Adjust two screw nuts(B, Fig.24) located on the endgear side of the headstock. Loose one and tighten the other. Make another cut. Keep adjusting screw nuts after each cut until the bar stock measurements are the same. Tighten all headstock screws.



Removing Gap Section

1. To remove gap section, locate two nuts (A, Fig.25) in the center of the gap section.
2. Using an open end wrench, tighten the two nuts. This will cause the taper pins to release. Remove the taper pins.
3. Remove six hex socket cap screws (B, Fig.25) with a hex key wrench.
4. Gap section can now be removed.

Installing Removable Gap Section

1. Clean the bottom and the ends of the gap section thoroughly.
2. Set gap section in place and align.
3. Remove nuts from the taper pins.
4. Slide taper pins in their respective holes and seat using a mallet. Install nuts on the taper pins finger tight.
5. Install four socket head cap screws and tighten securely.




Fig.25

Belt Replacement and Adjustment

1. Disconnect machine from the power source.
2. Remove end gear cover and lower rear cover on the headstock side.
3. Take tension off old belts by loosening two motor mount plate screws(A, Fig.26).
4. Remove belts. Install new belts onto pulleys.
5. Tension by tightening motor mount plate screws until light finger pressure causes approximately $3/4"$ deflection on each belt.
6. Install covers and connect lathe to the power source.




Fig.26




Fig.27

Aligning Tailstock to Headstock

Before proceeding, headstock should be aligned. See section labeled "Headstock Alignment".

1. Fit a 12" ground steel bar between centers of the headstock and tailstock. (See Fig.27)
2. Fit a dial indicator to the top slide and traverse the center line of the bar.
3. If adjustment is needed, align the tailstock using the off set screws(A, Fig.28) until the tailstock is aligned.






Fig.28


Headstock Assembly



Headstock Assembly



Headstock Assembly



Headstock Assembly


Index Part

NO.	NO.	Description	Size	Qty
1.....	04-01.....	Head Casting.....		1
2.....	04-04.....	Headstock Cover.....		1
3.....	04-09.....	Gasket.....		1
4.....	GB70.....	Hex Socket Cap Screw.....	M6x35.....	10
5.....	04-72.....	Gear Shift Shaft.....		1
6.....	04-02.....	Gear Shift Shaft.....		1
7.....	GB77.....	Set Screw.....	M8x12.....	2
8.....	GB2089-1x5x22.....	Spring.....		2
9.....	GB3080-6.....	Steel Ball.....	6.....	2
10.....	04-89.....	Block.....		1
11.....	GB78.....	Set Screw.....	.45x12.....	1
12.....	GB879-5x30.....	Taper Pin.....		5
13.....	04-96.....	Shift Fork.....		1
14.....	04-87.....	Gear.....	.45T.....	1
15.....	GB78.....	Set Screw.....	M6x6.....	3
16.....	GB3452.1.....	O-Ring.....	14x2.65.....	4
17.....	04-75.....	Shift Lever.....		1
18.....	04-08.....	Shift Lever.....		1
19.....	04-07.....	Gear Shifter.....		1
20.....	04-76.....	Gear Shifter.....		1
21.....	04-93.....	Shift Crank.....		1
22.....	04-94.....	Crank Pin.....		1
23.....	GB3452.2.....	O-Ring.....	11.2x2.65.....	1
24.....	GB1096.....	Key.....	4x10.....	1
25.....	GB70.....	Hex Socket CSP Screw.....	M6x12.....	8
26.....	04-62.....	Retaining Clip.....		2
27.....	04-97.....	Shifting Hub.....		2
28.....	GB4141.14.....	Handle Knob.....	10x50.....	4
29.....	04-81.....	Handle Shaft.....		2
30.....	04-98.....	Shifting Body.....		1
31.....	04-80.....	Handle Shaft.....		1
32.....	04-68.....	Inner Ring.....		1
33.....	04-88.....	Gear and Shaft Assembly.....	.35T.....	1
34.....	GB3452.3.....	O-Ring.....	26.5x2.65.....	1
35.....	GB70.....	Hex Socket Cap Screw.....	M12x35.....	4
36.....	04-82.....	Alignment Bolt.....		2
37.....	04-83.....	Alignment Block.....		1
38.....	GB5781.....	Alignment Bolt.....	M10x40.....	2
39.....	04-84.....	Drain Plug.....		1
40.....	04-73.....	Shift Fork.....		1
41.....	04-72.....	Shifting Crank.....		1
42.....	04-71.....	Shift Fork.....		1
43.....	04-70.....	Shifting Crank.....		1
44.....	GB1096.....	Key.....	5x18.....	1


45.....	GB30809.....	Steel Ball.....	9.....	2
46.....	GB2089-0.9x9x40.....	Sping.....		2
47.....	04-67.....	Shaft.....		1
48.....	GB3452.4.....	O-Ring.....	15x2.65.....	2
49.....	04-69.....	Shaft.....		1
50.....	04-63.....	Shaft.....		1
51.....	GB77.....	Set Screw.....	M12x1.....	2
52.....	04-68.....	Cover.....		1
53.....	04-95.....	Lever.....		1
54.....	04-61.....	Collar.....		1
55.....	04-21.....	Shaft(A).....		1
56.....	04-12.....	Washer.....		1
57.....	04-11.....	Pulley.....		1
58.....	GH1340A-11-10.....	Brake Block.....		1
59.....	GB879-5x25.....	Pin.....		1
60.....	11-09.....	Brake Actuator Shaft.....		1
61.....	GB896.6-12.....	Retainer Ring.....	12.....	1
62.....	11-15.....	Brake Shoe Assembly.....		1
63.....	GB894.1-12.....	Rerainer Ring.....	12.....	1
64.....	11-11.....	Brake Retainer Stud.....		1
65.....	TS-150305.....	Hex Socket Cap Screw.....	M6x20.....	6
66.....	HG4-692-67.....	Spacer.....	SD25x45x10.....	1
67.....	04-13.....	Cover.....		1
68.....	04-14.....	Gasket.....		1
69.....	GB894.2-25.....	Retainer Ring.....	25.....	5
70.....	BB6205.....	Ball Bearing.....		1
71.....	GB1096.....	key.....	8x20.....	1
72.....	GB1096.....	Key.....	8x50.....	2
73.....	GH1340-04-18.....	Key.....	7x50.....	1
74.....	TS-150404.....	Hex Socket Cap Screw.....	M8x20.....	1
75.....	GH1340A-04-15.....	Gear.....	38T.....	1
76.....	GH1340A-04-16.....	Gear.....	23T.....	1
77.....	GH1340A-04-17.....	Collar.....		1
78.....	GH1340A-04-19.....	Gear.....	30T.....	1
79.....	GH1340A-04-20.....	Gear.....	46T.....	1
80.....	BB-6204.....	Ball Bearing.....		4
81.....	GB894.2-20.....	Retainer Ring.....	20.....	1
82.....	04-40.....	Plug.....		1
83.....	GB3452.5.....	O-Ring.....	19x2.65.....	1
84.....	04-65.....	Shaft(B).....		1
85.....	04-53.....	Bearing Cap.....		2
86.....	04-52.....	Bearing Cap Gasket.....		2
87.....	04-64.....	Collar.....		1
88.....	GB894.2-50.....	Retainer Ring.....		2
89.....	04-66.....	Gear.....	39T.....	1
90.....	04-22.....	Gear.....	54T.....	1
91.....	04-23.....	Gear.....	47T.....	1
92.....	04-24.....	Gear.....	31T.....	1
93.....	04-25.....	Spacer.....		1
94.....	BB-6105.....	Ball Bearing.....		2
95.....	GB894.2-37.....	Retainer Ring.....		1
96.....	04-26.....	Gear.....	60T.....	1
97.....	GB1096.....	Key.....	8x28.....	1
98.....	04-27.....	Gear.....	21T.....	1
99.....	GB893.1-41.....	Retainer Ring.....		1
100.....	04-28.....	Plug.....		1
101.....	GB3452.6.....	O-Ring.....	40x3.55.....	1

102.....04-31.....	Spindle.....	1
103.....GB70.....	Hex Socket Cap Screw.....	6
104.....04-59.....	Spindle Bearing Cover.....	1
105.....04-60.....	Gasket.....	1
106.....GB70.....	Hex Soxket Cap Screw.....	2
107.....04-58.....	Lock Collar.....	1
108.....GB297.....	Tapered Roller Bearing.....	1
109.....04-57.....	Gear.....	1
110.....GB894.2-55.....	Retainer Ring.....	1
111.....04-32.....	Gear.....	1
112.....04-34.....	Gear.....	1
113.....04-33.....	Collar.....	1
114.....GB297.....	Tapered Roller Bearing.....	1
115.....04-30.....	Gasket.....	1
116.....04-29.....	Front Bearing Cover.....	1
117.....GB70.....	Hex Socket Cap Screw.....	3
118.....GB1096.....	Key.....	1
119.....GB1096.....	Key.....	1
120.....04-85.....	Camlock.....	3
121.....04-86.....	Camlock Set Pin.....	3
122.....GB1096-0.6x4x22	Sping.....	3
123.....GB70.....	Hex Socket Cap Screw.....	3
124.....04-37.....	Shaft(C).....	1
125.....GB3452.7.....	O-Ring.....	1
126.....GB1096.....	Key.....	1
127.....04-55.....	Gear.....	1
128.....04-54.....	Gear.....	1
129.....GB894.2-38.....	Retainer Ring.....	1
130.....04-36.....	Spacer.....	2
131.....04-35.....	Gear.....	1
132.....04-47.....	Shaft(D).....	1
133.....GB1096.....	Key.....	1
134.....04-46.....	Gear.....	1
135.....04-45.....	Collar.....	1
136.....04-44.....	Gear.....	1
137.....04-41.....	Gear.....	1
138.....04-39.....	Collar.....	1
139.....04-42.....	Shaft(E).....	1
140.....HG4-692-67A.....	Spacer.....	1
141.....04-49.....	Housing.....	1
142.....04-48.....	Housing Gasket.....	1
143.....BB-6104.....	Ball Bearing.....	2
144.....04-43.....	Gear.....	1


Gearbox Assembly



Gearbox Assembly (Inch system)



Gearbox(Metric system)




Gearbox Assembly


1.....05-63.....	Gearbox Casting.....	1
2.....05-61.....	Gasket.....	1
3.....05-07.....	Front Cover.....	1
4.....05-54.....	Cover.....	1
5.....GB819.....	Flat Head Machine Screw.....M4x10.....	8
6.....GB70.....	Hex Socket Cap Screw.....M8x40.....	1
7.....GB117.....	Pin.....	5x20.....
8.....GB70.....	Hex Socket Cap Screw.....M8x25.....	2
9.....GB117.....	Pin.....	5x28.....
10.....05-05.....	Locating Fork.....	1
11.....1000098.....	Spacer.....	1
12.....GB893.1-19.....	Retainer Ring.....	1
13.....05-51.....	Shaft.....	1
14.....05-03.....	Shifter.....	1
15.....GB70.....	Hex Socket Cap Screw.....M6x10.....	2
16.....05-13.....	Rack.....	1
17.....05-14.....	Gear.....	26T.....
18.....GB879-5x20.....	Pin.....	1
19.....05-55.....	Shift Fork.....	1
20.....GB79.....	Set Screw.....	M6x8.....
21.....05-56.....	Shift Lever.....	1
22.....GB879-5x20.....	Pin.....	1
23.....GB1096.....	Key.....	4x10.....
24.....05-57.....	Shaft.....	1
27.....GB78.....	Set Screw.....	M6x8.....
28.....05-02.....	Shaft.....	1
29.....GB78.....	Set Screw.....	M6x8.....
30.....05-12.....	Shift Fork.....	1
31.....05-01.....	Shift Key.....	3
33.....05-05.....	Locating Plate.....	1
34.....05-04.....	Control Plate.....	1
35.....05-60.....	Shift Hub.....	1
36.....GB1096.....	Key.....	4x10.....
37.....Q/2B285.3.....	Plug.....	1
38.....05-66.....	Cover.....	1
39.....05-59.....	Locating Disk.....	1
40.....05-10.....	Locating Disk.....	1
41.....05-58.....	Locating Disk.....	1
42.....GB819.....	Flat Head Machine Screw.....M5x10.....	6
43.....GB1160-12.....	Hub.....	1
44.....GB308-6.5.....	Steel Ball.....	9
45.....GB2089-0.8x5x25.....	Spring.....	4
46.....05-09.....	Shift Hub.....	2
47.....05-68.....	Shift Hub.....	1
48.....05-08.....	Washer.....	2
49.....05-08.....	Washer.....	1
50.....GB70.....	Hex Socket Cap Screw.....M6x16.....	7
51.....GB70.....	Hex Socket Cap Screw.....M6x16.....	1
52.....05-70.....	Indicator Disk.....	2
52A.....04-90.....	Indicator Disk.....	1
53.....GB818.....	Pan Head Machine Screw.....M3x6.....	6
54.....GB4141.14-BM10x50.....	Handle Cap.....	1
55.....05-69.....	Handle Shaft.....	1
56.....GB77.....	Set Screw.....	M8x8.....
57.....05-42.....	Retaining Clip.....	1

58.....05-41.....	Gear.....	52T.....	1
58A.....05-41/1.....	Gear.....	60T.....	1
59.....GB70.....	Hex Socket Cap Screw.....	6x20.....	3
60.....05-39.....	Flange.....		1
61.....05-38.....	Gasket.....		1
62.....BB-6104.....	Ball Bearing.....		1
63.....GB1096-5x14.....	Key.....		1
64.....05-40.....	Gear Shaft Assembly.....		1
65.....7000102.....	Ball Bearing.....		1
66.....05-36.....	Shaft Collar.....		1
67.....05-35.....	Gear.....	28T.....	1
68.....05-34.....	Gear.....	26T.....	1
69.....05-33.....	Gear.....	24T.....	1
70.....05-32.....	Gear.....	23T.....	1
71.....05-31.....	Gear.....	22T.....	1
72.....05-30.....	Gear.....	20T.....	1
73.....05-29.....	Gear.....	18T.....	1
74.....05-28.....	Gear.....	16T.....	1
75.....GB894.1-20.....	Retainer Ring.....		2
76.....BB-6202.....	Ball Bearing.....		4
77.....05-48.....	Gasket.....		2
78.....05-47.....	Flange.....		2
79.....05-52.....	Shaft.....		1
80.....GB893.1-32.....	Retainer Ring.....		2
81.....05-49.....	Gear.....	16T.....	1
82.....05-67.....	Shaft Collar.....		1
83.....BB-61.3.....	Ball Bearing.....		2
84.....05-37.....	Gear.....	26T.....	1
85.....GH1340A-05-66.....	Washer.....		1
86.....1000804.....	Bearing.....		2
87.....05-25.....	Gear.....	21T.....	1
88.....GB876-15.....	Retainer Ring.....		1
89.....05-19.....	Gear.....	36T.....	1
90.....05-53.....	Gasket.....		1
91.....05-17.....	Flange.....		1
92.....GB-3452.1-15x2.65.....	O-Ring.....		1
93.....BB-8104.....	Ball Bearing.....		2
94.....05-16.....	Shaft.....		1
95.....GB1096.....	Key.....	5x14.....	1
96.....GB1096.....	Key.....	6x14.....	1
97.....GB894.1-15.....	Retainer Ring.....		1
98.....05-26.....	Gear.....	16T.....	1
99.....05-24.....	Collar.....		1
100.....05-22.....	Gear.....	32T.....	1
101.....05-20.....	Nut.....		2
102.....05-53.....	Gasket.....		1
103.....05-18.....	Flange.....		1
104.....05-23.....	Shaft.....		1
105.....05-27.....	Shaft.....		1
106.....GB1096.....	Key.....	5x76.....	1
107.....05-67/1.....	Shaft Collar.....		1
108.....05-36/1.....	Gear.....	26T.....	1
109.....GB1096.....	Key.....	5x8.....	1
110.....05-27/1.....	Shaft.....		1
111.....05-40/1.....	Shaft.....		1

Apron Assembly



Apron Assembly




Apron Assembly

1.....	GB70.....	Hex Socket Cap Screw.....	M6x10.....	2
2.....	06-37.....	Half Nut.....		1
3.....	06-36.....	Bracket.....		1
4.....	GB70.....	Hex Socket Cap Screw.....	M6x16.....	2
5.....	GB78.....	Set Screw.....	M6x10.....	3
6.....	GB70.....	Hex Socket Cap Screw.....	M8x40.....	2
7.....	GB78.....	Set Srew.....	M8x8.....	1
8.....	06-39.....	Spring.....		1
9.....	GB308-6.....	Steel Ball.....	.6.....	1
10.....	06-01.....	Casting.....		1
11.....	GB4141.14-BM10x50.....	Knob.....		2
12.....	GH1340A-06-05.....	Handle Shaft.....		1
13.....	GB879.....	Pin.....	5x35.....	1
14.....	GB78.....	Set Screw.....	M6x6.....	1
15.....	GB879-5x50.....	Pin.....		1
16.....	06-29.....	Hub.....		1
17.....	06-40.....	Safety Catch.....		1
18.....	06-42.....	Half Nut Cam.....		1
19.....	Q/ZB285.3.....	Drain Plug.....		1
20.....	GB1160-12.....	Sight Glass.....		1
21.....	06-02.....	Plug.....		1
22.....	GH1340-06-16.....	Block.....		1
23.....	GB70.....	Hex Socket Cap Screw.....	M6x45.....	3
25.....	06-18.....	Handle Shaft.....		1
26.....	GH1340A-06-17.....	Spline Shaft.....		1
27.....	GH1340A-06-04.....	Bracket.....		1
28.....	GB70.....	Hex Socket Cap Screw.....	M6x12.....	2
29.....	GB70.....	Hex Socket Cap Screw.....	M6x16.....	2
31.....	GB1096-5x56.....	Key.....		1
32.....	GB879-3x5.....	Pin.....		2
33.....	06-27.....	Worm.....		1
34.....	06-34.....	Flange.....		2
35.....	GB70.....	Hex Socket Cap Screw.....	M6x12.....	2
36.....	06-33.....	Gib.....		1
37.....	06-44.....	Bushing.....		1
38.....	06-43.....	Shaft.....		1
39.....	GB894.1-16.....	Reainer Ring.....		1
40.....	06-28.....	Gear.....	22T.....	1
41.....	06-26.....	Collar.....		1
42.....	GB78.....	Set Screw.....	M6x6.....	1
43.....	GB879-5x35.....	Pin.....		1
44.....	GB1096-4x15.....	Key.....		1
45.....	06-19.....	Shaft.....		1
46.....	GB3452.1.....	Ring.....	17x1.8.....	1
47.....	GB896-12.....	Retainer Ring.....		1
48.....	06-10.....	Bushing.....		1
49.....	GB1340A-06-15.....	Cluster Gear.....	50T/20T.....	1
50.....	GB80.....	Set Screw.....	M8x8.....	1
51.....	06-14.....	Spring.....		1
52.....	GB608-6.....	Steel Ball.....	.6.....	1
53.....	GH1340A-06-13.....	Shaft.....		1
54.....	06-06.....	Shaft.....		1
55.....	06-08.....	Gear.....	50T.....	1
56.....	GB879-5x30.....	Pin.....		1
57.....	06-10.....	Bushing.....		1

58.....	GB894.1-16.....	Retainer Ring.....	1
59.....	06-11.....	Plug.....	1
60.....	06-07.....	Shaft.....	1
61.....	GB1096.....	Key.....	1
62.....	06-09.....	Wheel Flange.....	1
63.....	06-31.....	Indicator Ring.....	1
64.....	GB308-6.....	Steel Ball.....	2
65.....	06-32.....	Spring.....	2
66.....	GB4141.5-M10x80.....	Handle.....	2
67.....	GB78.....	Set Screw.....	1
68.....	06-30.....	Wheel Stud.....	1
69.....	06-12.....	Wheel.....	1
70.....	GB70.....	Hex Socket Cap Screw.....	3
71.....	06-20.....	Gear.....	1


Saddle and Cross Slide Assembly



Saddle and Cross Slide Assembly

1.....07-12.....	Plate w/Wiper.....	1
2.....GB827-2x8.....	Pan Head Screw.....	6
3.....07-07.....	Clamp Nut.....	2
4.....07-08.....	Hub.....	1
5.....GB70.....	Hex Socket Cap Screw.....M6x20.....	1
6.....07-05.....	Sleeve.....	1
7.....GB1155-8.....	Oiler.....	8
8.....07-01.....	Cross Slide Body.....	1
9.....07-28.....	Gib Adjusting Screw.....	2
10.....GB80.....	Set Screw.....	1
11.....GB70.....	Hex Socket Cap Screw.....M6x30.....	2
12.....GB6172.....	Hex Nut.....M10.....	2
13.....07-02.....	Bearing Cap.....	1
14.....BB-8101.....	Thrust Bearing.....	2
15.....07-03.....	Block.....	1
16.....07-25.....	Spacer.....	1
17.....07-06.....	Leadscrew.....	1
18.....GB70.....	Hex Socket Cap Screw.....M6x12.....	1
19.....07-22.....	Crossfeed Nut.....	1
20.....GB819.....	Pan Head Machine Screw.....M3x5.....	2
21.....07-21.....	Key.....	1
22.....07-20.....	Gear Shaft.....	1
23.....GB1096.....	Key.....4x20.....	1
24.....GB1155-6.....	Oiler.....	1
25.....GB827-2x8.....	Pan Head Screw.....M5x10.....	2
26.....07-14.....	Plate.....	1
27.....07-19.....	Housing.....	1
28.....BB-8102.....	Thrust Bearing.....	2
29.....07-18.....	Washer.....	1
30.....GB818.....	Pan Head Machine Screw.....M5x10.....	2
31.....07-17.....	Index Ring.....	1
32.....GB2089-0.7x5x9.....	Spring.....	2
33.....07-16.....	Compound Handle.....	1
34.....07-15.....	Cover Screw.....	1
35.....GB78.....	Set Screw.....M6x25.....	1
36.....GB4141.5-M10x80.....	Handle Knob.....	1
37.....GB70.....	Hex Socket Cap Screw.....M6x20.....	1
38.....GB1155-8.....	Oiler.....	4
39.....GH1340A-01.....	Cross Slide Body.....	1
40.....07-45.....	Hub.....	1
41.....07-31.....	Wiper.....	2
42.....GB70.....	Hex Socket Cap Screw.....M8x20.....	6
43.....07-24.....	Rear Pressure Plate.....	1
44.....07-23.....	Gib.....	1
45.....GB6170.....	Lock Nut.....M6.....	3
46.....GB78.....	Set Screw.....M6x20.....	3
47.....07-51.....	Wiper w/Plate.....	1
48.....GB818.....	Pan Head Machine Screw.....M5x10.....	8
49.....GB4141.14-M10x50.....	Knob.....	1
50.....07-46.....	Handle Shaft.....	1
51.....04-06.....	Oil Cap.....	1
52.....07-47.....	Lock Stud.....	1
53.....07-27.....	Front Pressure Plate.....	2
54.....07-38.....	Gib.....	1

~~Tool Post~~ ~~Slide~~ ~~Tool Post~~
Top Slide and Tool Post




TOP SLIDE AND TOOL POST

~~Saddle and Cross Slide Assembly~~

1.....07-32.....	Tool Post.....	1
2.....GB83-10x50.....	Tool Lock Screw.....	8
3.....GB4141.14-M10x50.....	Knob.....	1
4.....07-36.....	Handle Shaft.....	1
5.....07-33.....	Spacer.....	1
6.....07-34.....	Tool Post Pin.....	1
7.....07-29.....	Tool Post Position Pin.....	1
8.....GB2089-1x8x11.....	Spring.....	1
9.....07-37.....	Clamp Nut.....	1
10.....GB1155-8.....	Oiler.....	1
11.....07-49.....	Compound Slide.....	1
12.....GB70.....	Hex Socket Cap Screw.....	M6x20.....1
13.....07-09.....	Position Pin.....	1
14.....07-39.....	Nut.....	1
15.....GB1096-4x14.....	Key.....	1
16.....07-40.....	Compound Screw.....	1
17.....07-41.....	Screw Bushing.....	1
18.....GB70.....	Hex Socket Cap Screw.....	M6x20.....2
19.....BB-8103.....	Thrust Bearing.....	1
20.....07-42.....	Index Ring.....	1
21.....GB308-6.....	Steel Ball.....	6.....3
22.....GB2089-0.7x5x9.....	Spring.....	1
23.....07-43.....	Handle.....	1
24.....GB70.....	Hex Socket Cap Screw.....	M5x25.....1
25.....07-48.....	Handwheel.....	1
26.....07-15.....	Handle Screw.....	1
27.....GB78.....	Set Screw.....	M6x25.....1
28.....GB70-M5x40.....	Set Screw.....	M4x40.....1
29.....07-44.....	Handle	1
30.....GB80.....	Set Screw.....	M6x16.....1
31.....07-28.....	Gib Adjusting Screw.....	2
32.....GB70.....	Hex Socket Cap Screw.....	M8x16.....2
34.....07-10.....	Gib.....	1


Tailstock Assembly



Tailstock Assembly

1.....08-09.....	Index Ring.....	1
2.....GB70.....	Hex Socket Cap Screw.....M6x20.....	3
3.....08-08.....	Hub.....	1
4.....BB-8103.....	Thrust Bearing.....	1
5.....GB1096.....	key.....4x20.....	1
6.....08-05.....	Screw.....	1
7.....GB70.....	Hex Socket Cap Screw.....M6x16.....	2
8.....08-06.....	Flange.....	1
9.....GB4141.5-B10x50.....	Knob.....	2
10.....08-17.....	Lever Handle.....	1
11.....08-03.....	Eccentric Shaft.....	1
12.....GB879-5x12.....	Pin.....	1
13.....GB1155.....	Oiler.....10.....	2
14.....08-01.....	Tailstock Body.....	1
15.....08-20.....	Wheel.....	1
16.....GB4141.5-M10x80.....	Handle.....	1
17.....GB78.....	Set Screw.....M6x25.....	1
18.....08-12.....	Wheel Screw.....	1
19.....08-04.....	Spindle.....	1
20.....08-02.....	Stop Pin.....	1
21.....08-19.....	Gib.....	1
22.....08-18.....	Gib Adjusting Screw.....	2
23.....GB70.....	Hex Socket Cap Screw.....M8x45.....	2
24.....08-13.....	Tailstock Base.....	1
25.....08-14.....	Tailstock Clamp Plate.....	1
26.....GB95.....	Washer	12.....2
27.....GB5782.....	Hex Cap Bolt.....M12x75	1
28.....08-16	Block.....	1
29.....GB41	Nut.....	M6
30.....GB77.....	Set Screw	M6x16
31.....GB879.....	Pin	5x12
32.....08-15.....	Eccentric Shaft.....	1
33.....08-10	Lever Handle.....	1


Bed and Shaft Assembly



Bed and Shaft Assembly

1GB6172NutM81
2GB881Pin8x601
3GB70Hex Socket Cap ScrewM10x402
401-39Gap	1
5GB5781Hex Cap BoltM12x504
6GB70Hex Socket Cap ScrewM6x256
7GB879Pin5x356
801-07Rack	1
9Gb-1155-10Oiler101
10GB70Hex Socket Cap ScrewM8x552
11GB117Pin5x602
12GB79Set ScrewM8x101
1301-16Collar	1
1401-18Plug	2
1501-10Collar	1
1601-13End Bracket	1
1701-11Lead Screw	1
18GB879Pin5x352
1901-05Clutch	1
20GB308-6Steel Ball62
2101-38Spring	2
22GB79Set ScrewM8x102
2301-15Feed Shaft	1
2401-17Spindle Control Shaft	1
25GB4141.14-BM10x50Knob	1
2601-081/6Control Handle	1
27GB879Set Screw3x201
28GB41NutM62
29GB78Set ScrewM6x201
3001-086/6Control Fork	1
3101-084/6Control Bracket	1
32GB70Hex Socket Cap ScrewM6x162
3301-082/6Pin	1
34GB2089-0.8x5x25Spring	1
35GB78Set ScrewM8x81
36GB2089-3x35x70Spring	1
3701-085/6Sleeve	1
38GB79Set ScrewM3x62
3901-083/6Key	1
40GB79Set ScrewM6x101
4101-03Collar	1
4212-02Switch Box	1
43GB70Hex Socket Cap ScrewM6x202
44GB73Set ScrewM6x161
4501-28Shift Collar	1
46GB818Pan Head Machine ScrewM4x104
4712-03Cover Plate	1
48GB79Set ScrewM8x161
49GB2089-1x5x22Spring	1
50GB308-6Steel Ball61
5112-01Control Panel Assembly	1
52GB70Hex Socket Cap ScrewM8x252


Stand and Brake Assembly



Stand and Brake Assembly

1.....GB70.....	Hex Socket Cap Screw	M5x16.....	.8
2.....12-06.....	Electrical Box Cover.....		1
3.....01-09.....	Splash Guard.....		1
4.....GB70.....	Hex Socket Cap Screw.....	M6x10.....	.3
5.....GB70.....	Hex Socket Cep Screw.....	M6x10.....	.3
6.....GB6170.....	Hex Nut.....	M6.....	.4
7.....GB70.....	Hex Socket Cap Screw.....	M6x20.....	.4
8.....01-26.....	Bolt		1
9.....12-07.....	Electrical Box.....		1
10.....11-12.....	Pin.....		1
11.....GB896-6.....	Clip.....	6.....	1
12.....11-08.....	Connector Bar.....		1
13.....01-33.....	Chip Tray.....		1
13A.....GH1340-SP.....	Spacer.....		.6
14.....GB70.....	Hex Socket Cap Screw.....	M6x10.....	.4
15.....GB41.....	Hex Nut.....	M12.....	1
16.....GB97.2.....	Washer.....	12.....	1
17.....GB41.....	Hex Nut.....	M12.....	.1
18.....01-23.....	Screw.....		1
19.....01-22.....	Plate.....		1
20.....11-04.....	Spring.....		1
21.....GB70.....	Hex Socket Cap Screw	M6x10.....	.4
22.....01-34.....	Cover.....		1
23.....01-20.....	Pedestal (right).....		1
24.....01-01.....	Pedestal (left).....		1
25.....01-32.....	Bracket.....		1
26.....11-01.....	Shaft.....		1
27.....GB879.....	Pin.....	5x15.....	.4
28.....01-21.....	Front Plate.....		1
29.....GB70.....	Hex Socket Cap Screw	M6x10.....	.8
30.....11-023/3.....	Brake Pedal.....		1
31.....01-32.....	Bracket.....		1
33.....11-06.....	Link.....		1
34.....11-07.....	Link Nut.....		1
35.....11-05.....	Shaft Pin.....		1
36.....GB896-6.....	Retaining Clip.....		1
37.....01-24.....	Pulley.....		1
38.....01-02.....	Cover.....		1
39.....GB70.....	Hex Socket Cap Screw4
40.....01-25.....	Cover.....		1
41.....01-04.....	Cover Plate.....		1
42.....11-03.....	Shaft.....		1
43.....01-29.....	Shaft.....		1


End Gear Assembly



End Gear Assembly

1.....15-02A	Gear.....	40T.....	1
.....15-02B.....	Gear(Inch).....	45T.....	1
.....15-02C.....	Gear(Metric).....	32T.....	1
3.....GB70.....	Hex Socket Cap Screw.....	M5x16.....	1
4.....04-51.....	Washer.....		1
5.....04-50A.....	Gear(for GH-1340A Inch System).....	25T.....	1
.....04-50B.....	Gear(for GH-1440A Inch System).....	30T.....	1
.....04-50C.....	Gear(Metric System).....	24T.....	1
6.....05-46.....	Quadrant.....		1
7.....GB1096.....	Key.....	5x14.....	1
8.....05-43.....	Threaded Shaft.....		1
9.....BB-6103.....	Ball Bearing.....		2
10.....GB8931-35.....	Retaining Ring.....		2
11.....05-65.....	Gear.....	120/127T.....	1
12.....05-44.....	Washer.....		1
13.....GB6175.....	Nut.....	M10.....	1
14.....GB6175.....	Nut.....	M10.....	1
15.....GB1097.....	Stud.....	M10x80.....	2
16.....GB41.....	Nut.....	M12.....	2
17.....GB97.2.....	Washer.....	12-140HV.....	1
18.....01-36.....	Stud.....		1
19.....GB1096.....	Key.....	5x14.....	1
20.....05-41A.....	Gear(for GH-1340A Inch System).....	50T.....	1
.....04-41B.....	Gear.....	60T.....	1
21.....05-42.....	Washer.....		1
22.....GB70.....	Hex Sock Cap Screw.....	M6x16.....	1
23.....15-03A.....	Gear(Inch).....	32T.....	1
.....15-03B.....	Gear(Inch).....	40T.....	1
.....15-03C.....	Gear(Metric).....	65T.....	1
.....15-03D.....	Gear(Metric).....	66T.....	1
.....15-03E.....	Gear(Metric).....	70T.....	1
25.....04-78.....	Gear Cover.....		1
26.....04-77.....	Lock Knob.....		1
27.....GB70.....	Hex Sock Cap Screw.....	M6x25.....	1
28.....GB6172.....	Nut.....	M6.....	1


Threading Dial Assembly(Inch system)



Threading Dial Assembly(Inch system)

1.....09-01.....	Indicator Dial.....	1
2.....09-02.....	Dial.....	1
3.....GB879-3x12.....	Pin.....	1
4.....09-03.....	Shaft.....	1
5.....GB879-5x20.....	Pin.....	1
6.....09-04.....	Gear.....	1
7.....09-05.....	Body.....	1
8.....GB70.....	Hex Socket Cap Screw.....	1


(metoy) Threading Dial Assembly(Metric system)



Threading Dial Assembly(Metric system)

1.....09-11.....	Body.....	1
2.....GB70.....	Hex Socket Cap Screw.....	M6x60.....
3.....09-12.....	Indicator Dial.....	1
4.....09-13.....	Shaft.....	1
5.....09-14.....	Gear.....	21T.....
6.....09-15.....	Gear.....	22T.....
7.....09-16.....	Gear.....	26T.....
8.....09-17.....	Gear.....	27T.....
9.....09-18.....	Collar.....	1
10.....09-19.....	Gear.....	20T.....
11.....09-20.....	Washer.....	1
12.....GB70.....	Hex Socket Cap Screw.....	M6x16.....


Follow Rest



Follow Rest

1.....10B-03.....	Knob.....	2
2.....GB78.....	Set Screw.....	2
3.....10B-04.....	Bushing.....	2
4.....10B-05.....	Screw.....	2
5.....10B-02.....	Sleeve.....	2
6.....10B-06.....	Brass Finger.....	2
7.....GB6170.....	Hex Nut.....	2
8.....GB79.....	Set Screw.....	2
9.....10B-01.....	Body Casting.....	1
10.....GB70.....	Hex Socket Cap Screw.....	2


Steady Rest



Steady Rest


1.....10A-04.....	Knob.....	3
2.....GB78.....	Set Screw.....	3
3.....10A-05.....	Bushing.....	3
4.....10A-06.....	Screw.....	3
5.....10A-07.....	Sleeve.....	3
6.....10A-08.....	Brass Finger.....	3
7.....10A-03.....	Upper Body Casting.....	1
8.....GH1340A-08SR.....	Pin.....	1
9.....GB6170.....	Hex Nut.....	3
10.....GB79.....	Set Screw.....	3
11.....10A-01.....	Lower Body Casting.....	1
12.....GB70.....	Hex Socket Cap Screw.....	1
13.....GB97.1.....	Flat Washer.....	1
14.....GB6170.....	Hex Nut.....	1
15.....GB97.1.....	Flat Washer.....	1
16.....10A-02.....	Lock Pin.....	1
17.....10A-09.....	Clamp Plate.....	1
18.....GB97.1.....	Flat Washer.....	1
19.....GB5872.....	Hex Cap Bolt.....	1

Electrical Components



1.....GH1340A-KM1.....	Magnetic Starter(forward).....	1
2.....GH1340A-KM2.....	Magnetic Starter(reverse).....	1
3.....GH1340A-KM3.....	Coolant Pump Contactor.....	1
4.....GH1340A-KA1.....	Control Contactor.....	1
5.....GH1340A-FUSE.....	2 Amp Fuse.....	local purchase..... 1
6.....GH1340A-FR1.....	Motor Overload Relay.....	1
7.....GH1340A-FR2.....	Coolant Pump Overload Relay.....	1
8.....GH1340A-TC.....	Control Transformer.....	1
9.....GH1340A-SQ2.....	Door Switch.....	1
10.....GH1340A-QS1.....	Power On/Off Switch.....	1
11.....GH1340A-SQ3.....	Brake Switch.....	1

Electrical Components




1.....GH1340A-SB1.....	Off Switch.....	1
2.....GH1340A-SB2.....	Jog Switch.....	1
3.....GH1340A-HL.....	Power Indicator Light.....	1
4.....GH1340A-SA1.....	Coolant Pump Switch.....	1
5.....GH1340A-SQ1.....	2-Speed Hight/Low Switch.....	1
6.....GH1340A-SQ4.....	Forward Switch.....	1
7.....GH1340A-SQ5.....	Reverse Switch.....	1
.....GH1340A-M1.....	Main Motor(not shown).....	1
.....GH1340A-M2.....	Coolant Pump Motor(not shown).....	1

Part No.	Description	Quantity
1.....GH1340A-SB1.....	Off Switch.....	1
2.....GH1340A-SB2.....	Jog Switch.....	1
3.....GH1340A-HL.....	Power Indicator Light.....	1
4.....GH1340A-SA1.....	Coolant Pump Switch.....	1
5.....GH1340A-SQ1.....	2-Speed Hight/Low Switch.....	1
6.....GH1340A-SQ4.....	Forward Switch.....	1
7.....GH1340A-SQ5.....	Reverse Switch.....	1
.....GH1340A-M1.....	Main Motor(not shown).....	1
.....GH1340A-M2.....	Coolant Pump Motor(not shown).....	1

Electrical Schematic Symbol Glossary

Symbol	Component	Location
SB1	Off Switch	Front Panel
SB2	Jog Switch	Front Panel
HL	Power Indicator Light	Front Panel
EL	Machine Lamp	On carriage
SQ3	Brake Switch	Inside Bottom Cover-Headstock End
SQ2	Door Switch	Inside Change Gear Cover
SQ4	Forward Switch	Inside Change Gear Cover
SQ5	Reverse Switch	Inside Change Gear Cover
QS1	Power On/Off Switch	On Electrical Panel Cover-Rear Of Machine
SQ1	2-Speed High/Low Switch	Under Headstock on Stand
SA1	Coolant Pump Switch	Front Panel
KM3	Coolant Pump Contactor	Electrical Control Box-Rear of Machine
KA1	Control Contactor	Electrical Control Box-Rear of Machine
FR1	Motor Overload Relay	Electrical Control Box-Rear of Machine
FR2	Coolant Pump O/L Relay	Electrical Control Box-Rear of Machine
KM1	Magnetic Starter-Forward	Electrical Control Box-Rear of Machine
KM2	Magnetic Starter- Reverse	Electrical Control Box-Rear of Machine
TC	Control Transformer	Electrical Control Box-Rear of Machine
M1	Main Motor	Inside Stand - Headstock End
M2	Coolant Pump Motor	Inside Stand - Tailstock End




Electrical Schematic(For 3Ph only)

C Toy 2 mot

Motor Capabilities

CB B60 → 300mA 400VAC
CD60 → 150mA 250VAC



Electrical Schematic(For 1Ph only)



WARRANTY

CRAFTEX 2 YEAR LIMITED WARRANTY

Craftex warrants every product to be free from defects in materials and agrees to correct such defects where applicable. This warranty covers **two years** for parts and 90 days for labour (unless specified otherwise), to the original purchaser from the date of purchase but does not apply to malfunctions arising directly or indirectly from misuse, abuse, improper installation or assembly, negligence, accidents, repairs or alterations or lack of maintenance.

Proof of purchase is necessary.

All warranty claims are subject to inspection of such products or part thereof and Craftex reserves the right to inspect any returned item before a refund or replacement may be issued.

This warranty shall not apply to consumable products such as blades, bits, belts, cutters, chisels, punches etceteras.

Craftex shall in no event be liable for injuries, accidental or otherwise, death to persons or damage to property or for incidental contingent, special or consequential damages arising from the use of our products.

RETURNS, REPAIRS AND REPLACEMENTS

To return, repair, or replace a Craftex product, you must visit the appropriate Busy Bee Tools showroom or call 1-800-461-BUSY. Craftex is a brand of equipment that is exclusive to Busy Bee Tools.

For replacement parts directly from Busy Bee Tools, for this machine, please call 1-800-461-BUSY (2879), and have your credit card and part number handy.

- All returned merchandise will be subject to a minimum charge of 15% for re-stocking and handling with the following qualifications.
- Returns must be pre-authorized by us in writing.
- We do not accept *collect* shipments.
- Items returned for warranty purposes must be insured and shipped pre-paid to the nearest warehouse
- Returns must be accompanied with a copy of your original invoice as proof of purchase. Returns must be in an un-used condition and shipped in their original packaging a letter explaining your reason for the return. Incurred shipping and handling charges are not refundable.
- Busy Bee will repair or replace the item at our discretion and subject to our inspection.
- Repaired or replaced items will be returned to you pre-paid by our choice of carriers.
- Busy Bee reserves the right to refuse reimbursement or repairs or replacement if a third party without our prior authorization has carried out repairs to the item.
- Repairs made by Busy Bee are warranted for 30 days on parts and labour.
- Any unforeseen repair charges will be reported to you for acceptance prior to making the repairs.
- The Busy Bee Parts & Service Departments are fully equipped to do repairs on all products purchased from us with the exception of some products that require the return to their authorized repair depots. A Busy Bee representative will provide you with the necessary information to have this done.
- For faster service it is advisable to contact the nearest Busy Bee location for parts availability prior to bringing your product in for repairs.